

**LEVEL 1 CERTIFICATES – MEETING OF MARCH 18, 2010**

<b>PROPERTY ADDRESS</b>	<b>DISTRICT</b>	<b>APPLICANT</b>	<b>CERTIFICATE NO.</b>	<b>WORK DESCRIPTION</b>
229 E. Scott Avenue	Old North Knoxville H-1	Lauren & Steven Rider	20510ONK	Re-install original screen doors to back and front door; Repair and replace in kind rotten wood on upper porch on front of house, as needed, including repair piers on second story balcony
501 E. Oklahoma Avenue	Old North Knoxville H-1	Judy Gerstmeyer	22310ONK	Repair garage/carport at rear of lot, including sagging roof.
721 Luttrell Street	4 <sup>th</sup> & Gill H-1	Thomas Williams	216104&G	Repair or replace siding in kind, as necessary; Install trim on columns to replicate bases and capitals; install beadboard porch ceiling.
918 Eleanor Street	4 <sup>th</sup> & Gill H-1	Ron Hall	301104&G	Exterior rehabilitation, including new roof (with roof decking as required) altering present tin roof covering to shingle; removal of asbestos shingles and substitution with wood lap siding with 4" reveal; repair and replace existing wood siding as necessary, matching historic sizes and installation; install color-clad downspouts and gutters; repair masonry as necessary, using low Portland-content mortar to match historic mortar.  NOTE: Applicant has indicated an interest in constructing a small rear addition that will serve as storage and not be visible from the front of the house; he intends to submit information for that addition to the HZC in several months.

<b>PROPERTY ADDRESS</b>	<b>DISTRICT</b>	<b>APPLICANT</b>	<b>CERTIFICATE NO.</b>	<b>WORK DESCRIPTION</b>
1904 Washington Avenue	Edgewood-Park City H-1	Charles B. Hassenboehler	21610EDG	Repair foundation; remove second story front added room and restore porch, if it was a porch, adding window to match historic windows; siding repair in kind; repair windows; remove added front door, replacing with matching window; remove storm door; remove rear fire stair.  REISSUE OF CERTIFICATE NO. 20608EDG.
1 Market Square	Market Square H-1	J & R Masonry	22210MKT	Removal of chimney on rear wall, not visible from Union or Market. Chimney is collapsing into alley, causing a pedestrian and vehicular hazard. Applicant has been informed that chimney should be rebuilt when additional masonry work is performed on building. Will be torn down to approximately 18-24" above roofline.
31 Market Square	Market Square H-1	Andy Asbury (Vexus Sign Company)	22510MKT	Install blade sign, approximately of 6 sq. ft. (approximately 2' x 3'), double faced, painted aluminum, on wrought iron bracket (frame) hanging from front of building..