

Staff Report - Certificate of Appropriateness Application

Knoxville Historic Zoning Commission

File Number: 3-F-20-HZ

PROPERTY LOCATION: 215 Sixteenth St. / Parcel ID 94 N E 019

DISTRICT: Ft. Sanders NC-1

MEETING DATE: 3/19/2020

APPLICANT: John Holmes

LEVEL OF WORK: Level II. Major repair or replacement of materials or architectural elements

PROPERTY DESCRIPTION: Queen Anne cottage, c.1910.

One-story frame residence with an exterior of vinyl siding. Hipped roof with lower cross gables, and a sawn wood attic vent and cornice in the front gable. Two-over-two, double-hung windows. One-story, one-half porch with turned wood columns. Interior offset brick chimney, brick foundation.

► DESCRIPTION OF WORK:

- Demolition of rear (west) elevation shed-roof stoop.
- Construction of rear (west elevation) addition: addition will measure 12'-7" wide by 7'-3" deep and feature a shed roof, with a 24" by 24" casement window on the rear elevation of the addition. Addition will also require relocation of the rear door and rear elevation window to the gable-roof massing to the right.
- Reconstruction of front porch (east elevation): existing porch will be demolished and be reconstructed with a foundation clad in brick veneer, new 6" by 6" square posts to match existing, and a square picket railing. Wood steps will be removed and reconstructed with handrails to match railing.
- Windows: existing windows will be replaced with one-over-one, double-hung vinyl windows. Attic vents proposed to be replaced with egress windows on façade and side (north, east, and south) gable fields. Egress windows to be 36" x 42". Façade first story will receive additional double-hung window, 36" by 72". Several side windows proposed to be partially or fully enclosed.

► APPLICABLE DESIGN GUIDELINES:

Fort Sanders NC-1, adopted by the Knoxville City Council on September 13, 2000.

Roofs

- 3. Use roofing materials that are in keeping with the historic development styles. Asphalt shingle, tile, pressed metal, and slate were used.
- 4. Darker shades of shingles were historically used and should be selected in new construction.

Porches



Staff Report - Certificate of Appropriateness Application

Knoxville Historic Zoning Commission

File Number: 3-F-20-HZ

- 1. Provide porches with proportions and materials that complement pre-1940 housing. For clapboard-type construction, wood is the most appropriate primary material. Brick or cut stone are appropriate as foundations or in columns supports.
- 2. Porches should be no less than 6 feet deep and no more than 10 feet deep.

Wall Materials

- 2. Clapboard (or clapboard-like materials such as aluminum or vinyl), shingle (or shingle-like materials), or brick should be used.
- 5. In making additions to existing buildings, wall cladding should complement the original wall covering. Acceptable materials are clapboard, vinyl siding, cement fiber board, brick and stucco.

Windows and Entrances

- 1. Window proportions and symmetry should be similar to the pre-1940 styles in the neighborhood.
- 2. Windows should be double-hung sash windows. Vinyl or metal-clad windows may be used in place of wood frame windows.
- 2 [sic]. Egress windows will have to be designed to comply with fire/building code provisions.
- 3. Accent windows are appropriate with new construction.
- 4. Double-hung sash windows are recommended for two- to three-story new construction.
- 5. Variations of double-hung windows should be considered in relation to the design of new buildings.
- 6. The proportions of upper-level windows should not exceed the proportion of the first level.
- 9. Entrances to the building should be provided from the street, using doors that have similar proportions and features to pre-1940 architecture.
- 10. When parking areas are provided behind buildings, rear entrances are also allowed.

Parking

2. Provide parking access off the alley or off a side street.

Additions to Existing Buildings

- 1. Additions should be made to the rear or side of the building.
- 3. Transitional space shall be provided between the addition and the existing structure. ... The wall of the new connecting structure should not be continuous with the wall of the existing building, but have a minimum 4' x 6' indentation.
- 4. Bays at least two feet in depth shall be provided for 50% of the side façade.
- 5. Windows or French doors and balconies shall provide 10% to 20% transparency on the sides of buildings.

COMMENTS:

N/A

STAFF FINDINGS:

1. The house is a contributing resource to the Fort Sanders NC Overlay and National Register Historic District.



Staff Report - Certificate of Appropriateness Application

Knoxville Historic Zoning Commission

File Number: 3-F-20-HZ

- 2. The rear shed-roof stoop is not a historic feature of the house and does not contribute to the house's overall integrity. Demolition of the existing shed roof and concrete block foundation for purposes of an addition is appropriate.
- 3. The rear addition is modest and does not detract from the overall architectural integrity of the house. It is sufficiently offset from the south elevation to differentiate it from the historic house. The proposed rear addition will feature materials that are appropriate within the guidelines. The rear addition should retain a shed roof similar to the existing or the addition constructed at 207 16th, instead of the hipped roof on the renderings.
- 4. The proposed egress windows meet the minimum size requirement for building code. While applicant has installed egress windows in side gable fields in multiple instances in the Fort Sanders overlay, a full-sized egress window of 36" by 42" is not appropriate for the façade front gable. The renderings provided by applicant are not to scale and the proposed egress window would be too large for the historic proportions of windows.
- 5. The proposed replacement 1/1 vinyl windows are appropriate under the Fort Sanders NC guidelines. However, partially enclosing the paired windows on the south elevation does not retain window proportions and symmetry that reflects the historic context.
- 6. Applicant has sufficiently documented deterioration of foundation under the bay window, porch, and shed roof; reconstruction in these locations is appropriate. However, if the scope of reconstruction exceeds that described in the application, applicant will need to submit additional information for review by staff or HZC.

► STAFF RECOMMENDATION:

Staff recommends approval of the work proposed, with the following conditions: 1) omit egress window in façade (east) gable field (smaller casement window for natural light, if necessary, could be approved by staff); 2) paired windows on south elevation remain the same size as the original windows; 3) reconstructed front porch retain shed roof and square columns as existing; 4) if foundation must be reconstructed in locations other than front porch, under façade bay window, and rear addition, a revised application for a COA be submitted; 5) final drawings submitted for permitting to match specifics of the proposed construction, including final window placement and size; a shed-roof porch; and a shed-roof rear addition

Page 3 of 3 3-F-20-HZ 3/11/2020 1:15:33 PM





APPLICATION FOR CERTIFICATE OF APPROPRIATENESS




215 Sixteenth St. 37916

Ft. Sanders NC-1

Original Print Date: 3/3/2020

Knoxville/Knox County Planning -- Historic Zoning Commission





DESIGN REVIEW REQUEST

- DOWNTOWN DESIGN (DK)
- HISTORIC ZONING (H)
- INFILL HOUSING (IH)

John Holmes			
Applicant			
2/28/20	March 19, 2020	3-F-20-HZ	
Date Filed	Meeting Date (if applicable)	File Number(s)	
CORRESPONDENCE			
All correspondence related to this applicat	ion should be directed to the approved co	ntact listed below.	
Owner 🗌 Contractor 🗎 Engineer	☐ Architect/Landscape Architect		
John Holmes			
Name	Company		
5914 Gray Gables Dr		TN	37931
Address	City	State	Zip
423-231-4980	jholmes6@gmail.com		
Phone	Email		
Evian Partners	PO Box 1335	5 423-231-1266	
Owner Name (if different from applicant)	Owner Address	Ov	vner Phone
215 16th St.	09-	4NE019	
Property Address	Par	cel ID	
Fort Sanders	RN5-NC-1		
Neighborhood	Zor	ning	
AUTHORIZATION			
0. 1. 0. 1.11			1-
Linday Crockett Staff Signature	Lindsay Crocke	H 3/	2/20
Staff Signature \bigvee	Please Print	Da	te
11 011			
John Mhm	John Holmes	1	1/25/19

REQUEST

DOWNTOWN DESIGN	Level 1: ☐ Signs ☐ Alteration of an existing building/structure Level 2: ☐ Addition to an existing building/structure Level 3: ☐ Construction of new building/structure ☐ Site design, parking, plazas, landscape in the second process of the				
HISTORIC ZONING	Level 1: Signs Routine repair of siding, windows, roof, or other features, in-kind; Installation of gutters, storm windows/doors Level 2: Major repair, removal, or replacement of architectural elements or materials Additions and accessory structures Level 3: Construction of a new primary building Level 4: Relocation of a contributing structure Demolition of a contributing structure See required Historic Zoning attachment for more details. Brief description of work:				
INFILL HOUSING	Level 1: Driveways, parking pads, access point, garages or similar facilities Subdivisions Level 2: Additions visible from the primary street Changes to porches visible from the primary street Level 3: New primary structure Site built Modular Multi-Sectional See required Infill Housing attachment for more details. Brief description of work:				
STAFF USE ONLY	ATTACHMENTS Downtown Design Checklist Historic Zoning Design Checklist Infill Housing Design Checklist ADDITIONAL REQUIREMENTS Property Owners / Option Holders Level 1: \$50 • Level 2: \$100 • Level 3: \$250 • Level 4: \$500	FEE 1: FEE 2: FEE 3:	TOTAL:		

Level 1:

Tongue and groove flooring for front porch, stained beadboard ceiling new handrails (Picture of railings style included below)

Replace windows with 1/1 double hung windows (Jeld wen vinyl 2500 series or equal)

Replace attic vent with egress window on the gables, minimum size of 36"x42" high)

Replace vinyl siding with Hardi siding, new sheeting

Replace fascia, soffits, and gutters, fascia and soffits will be Hardi

Repair foundation brick, paint or stucco as necessary.

Replace front and rear door

Replace the roof, remove old shingles (6 layers), new sheathing over existing 1' slat boards, new drip edge, asphalt shingles

Rebuild front steps, including handrails

Remove chimney below roof line

Front Gable window is 36"x42" casement for egress

Side gable windows 36"x42" Casement for egress.



Level 2:

Remove and rebuild front porch and roof with same dimensions. New 6"x6" square posts to match existing. See pictures documenting the poor condition. The brick wall is collapsing inwards and will have to be rebuilt. There are no footers under the brick and will collapse again if not properly rebuilt. Porch ceiling is rotten and will need to be replaced as well. Front porch foundation will be 8" CMU with brick façade.

New foundation under window box, it is currently supported with assorted blocks and bricks.

Remove and rebuild rear porch and enclose, no addition to the existing lot coverage. The existing concrete is deteriorating severely and appears to have no footers underneath the walls. Remove the existing shed roof over the rear porch and rebuild shed roof (like 203 and 207 16th next door) with 4:12 pitch. 30"x30" window on rear bathroom. Matches the sister houses next door at 207 16th and 203 16th.


THIS SURVEY WAS PREPARED USING A COMBINATION OF TOTAL STATION AND R.T.K. G.P.S. DATA COLLECTION. G.P.S. RECEIVER INFO.: SOKKIA MESA S/N 144387, TOPCON ANTENNA:

PG-S1. TOTAL STATION: TOPCON GPT-8205A VERTICAL DATUM IS NAVD88, GEOID12

IPN = IRON PIN, NEW R/W = RIGHT-OF-WAY



SIXTEENTH STREET



TIFICATION OF CATEGORY AND ACCURACY OF SURVEY

SURVEY FOR EVIAN PARTNERS

DIST. 4 WARD 10 CITY OF KNOXVILLE ADDRESS 215 SIXTEENTH STREET **KNOX** COUNTY PART 107 LOT NO.__ __ BLOCK . .UNIT . RAMSEY'S ADDITION

INSTR. PC "A 172B SCALE 1"= 20" ORDERED BY: INDEP. JOB NO. 1908010

HINDS SURVEYING CO.

3555 WINDY J FARMS DR. LOUISVILLE, TN 37777
PH. 588-9799 FAX. 233-3393 © CONTROL 2019. STALL. WWW.HINDSSURVEYING.COM



DATE _

8-19


2019



Elevations:




West




South





North




Elevations:










PRELIMINARY - NOT

APPROVED Comall Rear Yard Facing West)

215 16th St - Cottage 4BR 3BA (EVIP) 16ST215

MAIN LEVEL



MAIN LEVEL NOTES:

Insulation: (Fibergiss Batts)

Malls - R20

(Entire house wall sheathing will be replaced) Ceilings - R49 flats (R-30 Attic sloped areas) Floors - R19

Crawlspace walls - R-10 XPS interior 1/2" OSB sheething per R316.5.4

Heat/Cooling:

14 Seer Split 50.000 BTU Gas furnace R-8 Duct insulation Duct test required

Electric 50aallon electric

36"w × 72"H SHGC - 28

No windows required to be tempered IRC302.1(1) - No windows <3' from property line

7/16 OSB Sheathing 2x2 added to exterior walls so that R20 insulation may be properly installed Vapor Barrier Hardi Sidina

Framing: Exterior walls existing 2x4 rough cut @ 16"O.C. 2x2 added to existing exterior walls for insulation depth New Exterior walls 2x6 @ 16" O.C. New interior walls 2x4 @ 16"O.C. Floor sheeting 3/4" OSB Headers are 2×12 (2) (longest span 60") Existing ceiling joists are rough cut 2x8 @ 24" Ceiling joists replaced with 2x12 #2 prime @ 16" O.C. Floor joists replaced with 2x12 #2 prime @ 16" O.C.

No changes, orginal framing @ 24" O.C. to remain new 2×10 collar ties and purlins to reinforce existing roof

2×10 sister on all orignal roof joists

Knee walls @ 4'

New 1/2" sheeting and shingles New roof over addition is stick built 2x10 @ 16" O.C.

All doors have min 36"min landing Rear of property is a 6'x20' paver patio Front entry is on the porch

Fire wall:

None required

Front Porch:

rebuild front porch and roof Stucco Front replace tongue and groove flooring Replace joists with 2x8 PT as needed.

3" PVC tee under vapor barrier installed through roof exten min of 1' above roof line

Door Landings:Front door and rear door shall have min 36"x36" clear landing Plans show 15'x9.5' for front door Rear door opens to paver patio 6'x20'





Façade view, photographer facing west

Northeast oblique





Southwest oblique, photographer facing northeast

Southeast oblique








South




West



Front Porch brick caving in (North side)



Front foundation collapsing (East) Supported by piecemeal brick and block



Front porch corner collapsing

