

LEVEL I CERTIFICATES of APPROPRIATENESS – HZC MEETING JANUARY 17, 2013

PROPERTY ADDRESS	DISTRICT	WORK DESCRIPTION
138 Leonard Place	Old North Knoxville-H-1	Remove existing fiberboard roof shingles as well as 3-tab asphalt shingles underneath. Replace with 3-tab asphalt shingles retaining asphalt-covered ridgelines. Replace guttering with hidden hangers.
808 N. 4 th	Fourth and Gill-H-1	Repair original siding and replace in-kind as needed. Repair rotted sash, rebuild muntins and reglaze as needed on original windows. Repoint brick foundation as needed. Remove stucco from brick porch piers and repair and tuckpoint brick. Tuckpoint remaining internal chimney. Remove stuccoed remains of fireplace in rear. Replace non-original center rear door with a salvaged wood door similar to front door. Remove rear side non-original door from kitchen and replace with window to match existing small non-operable window on south side toward front. Install 1/1 wood window (to match existing) approximately 32" wide by 4' tall into opening created by removal of fireplace remnants. Repair and rebuild existing late-added deck, balustrade and steps utilizing wood resin composite materials. Replace gutters.
1513 Highland Avenue	Fort Sanders-NC-1	Replace wood siding with vinyl siding to match size of existing (4"), paint brick foundation.