



Staff Report

Knoxville Historic Zoning Commission

File Number: 10-G-24-HZ

Meeting:	10/17/2024		
Applicant:	Andrew Randazzo		
Owner:	Andrew Randazzo		

Property Information

Location:1800 Jefferson Ave.Parcel ID82 P H 009District:Edgewood-Park City HZoning:RN-2 (Single-Family Residential Neighborhood)Description:Queen Anne, c.1900

One-and-one-half-story frame residence with a hipped roof clad in asphalt shingles, an exterior of aluminum siding, and a continuous foundation. Two gable-roof dormers are evenly spaced on the front roof slope. Centrally-located, front-gable roof portico.

Description of Work

Level II Major Repair or Replacement

Removal of two one-over-one, double-hung aluminum windows on the east elevation and four one-over-one, double-hung aluminum windows on the west elevation. Windows will be replaced with new, one-over-one, double-hung, aluminum-clad wood windows. On the west elevation, the replacement windows will be the same size as the existing. On the east elevation, two windows (center bay, first story) will be reduced in height by approximately 20".

Rear elevation door to be shifted to location of adjacent window.

Applicable Design Guidelines

Edgewood-Park City Design Guidelines, adopted by the Knoxville City Council on July 29, 1997.

Windows:

3. If replacement windows are necessary, they must be the same overall size as the originals, with the same pane division, and the same muntin style and exterior depth, width and profile. Thermal sash windows that use false muntins are not acceptable.

4. Windows shall not be replaced with fixed thermal glazing or be made inoperable.

7. Historic windows shall not be blocked in. If ceilings have been dropped, provide a setback to allow for the full height of the original window openings. Do not cut across an existing window with a new floor or ceiling, so that the outside appearance of the window is changed.

8. Reuse existing, serviceable window hardware.

Entrances:

2. It may be appropriate to design or construct a new entrance if the historic one is missing. Any restoration shall be based on historical, pictorial and physical documentation and be compatible with the historic character of the building.

3. A replacement entrance must not create a false historic appearance. A new entrance shall be compatible in size,

scale, materials and color.

4. Entrances shall not be removed when rehabilitating a building.

5. Service or rear entrances shall not be altered to make them appear more formal by adding paneled doors, fanlights or sidelights.

6. Secondary entrances shall be compatible with the originals in size, scale and materials.

Windows

4. If replacement is necessary, replace historic materials in kind.

d. It is not appropriate to enlarge or reduce the size of the original opening to accommodate the installation of a replacement window.

e. Replacement windows are to match the operation type (e.g., double-hung) of the original window.

f. Alternative materials for replacement windows may be considered, as long as the replacements match the overall size, muntin configuration and profile, meeting rail width and profile, and style of the original windows.

Comments

N/A

Staff Findings

1. 1800 Jefferson Ave is a contributing resource to the Park City National Register Historic District and the local overlay.

2. All work will be completed on secondary elevations. The secondary door to be moved is located on the rear elevation and will not be visible from the right-of-way.

3. The windows proposed to be replaced are not original to the house. The original Edgewood-Park City design guidelines recommend that replacement windows be "the same overall size as the originals, with the same pane division, and the same muntin style and exterior depth, width and profile," but do not specifically mention material. The revised but not yet adopted guidelines note that alternative materials may be considered, as long as they match the overall size, muntin profile and size, and style of the original windows. Based on these design guidelines, the proposed aluminum-clad wood material is appropriate.

4. On the east elevation, the windows are proposed to be reduced in length by 20" to accommodate kitchen fixtures below. Design guidelines typically discourage modifying the size of original windows, but the HZC has approved size modifications on a case-by-case basis. The windows proposed to be shortened will be somewhat visible from the right-of-way. They will not be removed entirely, and similarly-placed side elevation windows on adjacent houses are shorter than those on the façade. The Commission should discuss reducing the size of windows on the east elevation.

Staff Recommendation

Providing for discussion from the Commission on the east elevation windows, staff recommends approval of Certificate 10-G-24-HZ as submitted.



DESIGN REVIEW REQUEST

□ DOWNTOWN DESIGN (DK)

□ HISTORIC ZONING (H)

□ INFILL HOUSING (IH)

Andrew Randazzo

Applicant		
9-23-25	10-17-24	
Date Filed	Meeting Date (if applicable)	File Number(s)

CORRESPONDENCE

All correspondence related to this application should be directed to the approved contact listed below.

	Owner		Contractor		Engineer		Architect/Landscape Architect
--	-------	--	------------	--	----------	--	-------------------------------

Andrew Randazzo

Name		Company		
1800 Jefferson Ave		Knoxville	TN	37917
Address		City	State	Zip
865-776-6230	andrew.randazzo@gmail.com			
Phone	Email			

CURRENT PROPERTY INFO

Owner Name (if different from applicant)	Owner Address		Owner Phone
		082IL031	
Property Address		Parcel ID	
		RN-2/H	
Neighborhood		Zoning	

AUTHORIZATION

Lindsay	Crockett
Staff Signature	

Lindsay Crockett

Please Print

Date

9.30.24

Andrew Randazzo

Applicant Signature

Andrew Randazzo Please Print 9-30-24 Date

REQUEST

DOWNTOWN DESIGN	Level 1: Signs Alteration of an existing building/structure Level 2: Addition to an existing building/structure Level 3: Construction of new building/structure Site design, parking, plazas, landscape See required Downtown Design attachment for more details. Brief description of work:
HISTORIC ZONING	Level 1: Signs Routine repair of siding, windows, roof, or other features, in-kind; Installation of gutters, storm windows/doors Level 2: Major repair, removal, or replacement of architectural elements or materials Additions and accessory structures Level 3: Construction of a new primary building Level 4: Demolition of a contributing structure Berequired Historic Zoning attachment for more details. Brief description of work: - replacement of non-historic aluminum windows with wood windows. • Move rear entry door to existing rear window. Enclose old rear door with wood lap siding.
INFILL HOUSING	Level 1: Driveways, parking pads, access point, garages or similar facilities Subdivisions Level 2: Additions visible from the primary street Changes to porches visible from the primary street Level 3: New primary structure Site built Modular Multi-Sectional See required Infill Housing attachment for more details. Brief description of work:

	ATTACHMENTS	FEE 1:	TOTAL: \$100
F	Downtown Design Checklist	100.00	φ ± σ σ
Ō	Historic Zoning Design Checklist	FEE 2:	
: USE ONLY	Infill Housing Design Checklist		
Ë	ADDITIONAL REQUIREMENTS		
STAFF I	Property Owners / Option Holders	FEE 3:	
	Level 1: \$50 • Level 2: \$100 • Level 3: \$250 • Level 4: \$500		

Proposed Work:

Replace 2 east facing aluminum windows with wood windows.

New Windows: 29"x48" Double hung wood windows.

https://www.homedepot.com/p/JELD-WEN-29-375-in-x-48-in-W-5500-Double-Hung-Wood-Clad-Window-THDJW237700014/323082547

Replace 4 west facing aluminum windows with the same size wood windows.

Move the rear entry door to the existing rear window. Enclose the old doorway with wood lap siding.



East Facing Windows



Existing, aluminum windows 29x64"



Street view of east windows



Two lower center windows (29x64") are proposed to be replaced with two (29x44") wood double hung windows.

Product specs:

JELD-WEN 29.375 in. x 48 in. W-5500 Double Hung Wood Clad Window

★★★★★ (5) ∨ Questions & Answers (12)


















Window to be removed and replaced with existing rear door.



Existing rear aluminum window

