

**LEVEL 1 CERTIFICATES – MEETING OF FEBRUARY 18, 2010**

<b>PROPERTY ADDRESS</b>	<b>DISTRICT</b>	<b>APPLICANT</b>	<b>CERTIFICATE NO.</b>	<b>WORK DESCRIPTION</b>
726 Deery Street	4 <sup>th</sup> & Gill H-1	Josh Wright	126104&G	Repair or replace gutter system, as necessary.
806 Deery Street	4 <sup>th</sup> & Gill H-1	David Kerns	112104&G	Rebuilding collapsing foundation at rear corner, using Preservation Brief No. 2 with low Portland-content mortar.
1008 Luttrell Street	4 <sup>th</sup> & Gill H-1	Gil Negendank	128104&G	Repair or replace porch floor in kind, as necessary, removing columns to repair structure and reinstalling columns after repairs. Replace or repair front porch roof, as necessary.
1415 Fremont Place	Old North Knoxville H-1	Daniel Schuh	11910ONKA	Remove artificial siding and repair wood siding and trim in kind as necessary; repair and repoint masonry, using provisions of Preservation Brief No. 2, repair porch ceiling, floor and railings; replace roof if necessary, using asphalt shingles; repair or install gutters.
1421 Fremont Place	Old North Knoxville H-1	Daniel Schuh	11910ONKB	Repair siding, fascia, soffit & trim; repair masonry, using Preservation No. 2' reroof, using asphalt shingles; repair porch ceiling and floor in kind as necessary; install or repair gutters.

<b>PROPERTY ADDRESS</b>	<b>DISTRICT</b>	<b>APPLICANT</b>	<b>CERTIFICATE NO.</b>	<b>WORK DESCRIPTION</b>
409 E. Oklahoma Avenue	Old North Knoxville H-1	Steve Finnigan	12510ONK	<p>Remove fiber cement shingle siding and replace with wood lap siding with approximate 4" reveal, installing corner boards, window and door trim and skirt board, if necessary; Repair or replace gutters and downspouts; replace front door with halfview glass door.</p> <p>NOTE: Applicant understands that some window replacement will be necessary, and a redesign of the front gable opening is called for. An additional application will be made to answer those concerns.</p>
1726 Washington Avenue	Edgewood-Park City H-1	Mike Anderson	11110EDG	<p>Repair or replace wood siding and trim in kind as necessary; repair masonry using Preservation Brief No. 2 (low Portland-content mortar); replace roofing in kind, making any necessary repairs to roof decking and using dark shade of asphalt shingles.</p>