

LEVEL I CERTIFICATES – MEETING OF NOVEMBER 17, 2011

PROPERTY ADDRESS	DISTRICT	APPLICANT	CERTIFICATE NO.	WORK DESCRIPTION
628 Luttrell Street	4 th & Gill H-1	Max Grogan	1011114G	Replacement of wood porch flooring, in kind.
706 Luttrell Street	4 th & Gill H-1	Adam Scott	1031114G	Add new deck to rear of house made of wood or trex material; approximately 6 feet deep by 30 feet wide.
710 Deery Street	4 th & Gill H-1	Joe MacDonald	1006114G	Replace front porch roof with new metal roof materials to match. Replace all windows with new wood windows that are the same size and two-over-two grill pattern. Repair damaged siding, fascia, trim and soffit as needed, in kind. Add new aluminum five inch k-style gutters and downspouts.
831 Deery Street	4 th & Gill H-1	Andrew Schaeffer	101111A4G	In-kind replacement of roof.
941 Eleanor Street	4 th & Gill H-1	Ken Bronson Construction	1025114G	Level I (approved 10/25/2011) - Replace existing 3-tab asphalt shingles with new 3-tab or dimensional asphalt shingles. Replace existing EPDM roof in front of the roof dormer with new EPDM roof or flat metal roof. Repair front porch beam, trim and soffit in kind, as needed. Replace existing front porch EPDM roof with new EPDM roof. Replace plywood soffits on second story with new plywood in-kind, as

PROPERTY ADDRESS	DISTRICT	APPLICANT	CERTIFICATE NO.	WORK DESCRIPTION
				needed. Replace bead board soffit above second story bay window on the front façade in-kind, as needed. Replace wood trim along roofline on second story in-kind, as needed. Replace guttering in-kind, as needed.
1306 Kenyon Street	Old North Knoxville H-1	Susan Simpson	100711ONK	Repair and replace wood siding and cedar shingles on upper sides of the house in-kind, as needed. Restore or replace window trim in-kind, as needed.
309 E. Oklahoma Avenue	Old North Knoxville H-1	Kerns Construction Inc., David Kerns	110111ONK	Replace existing asbestos shingle roof on front of house with faux slate roof to match existing on back half of house. (Note: This is an emergency approval because of a leaking roof.)
417 Clark Street	Mechanicsville H-1	Melissa Hornsby	101811MEC	Repair wood porch flooring in kind.
1531 Forest Avenue	Fort Sanders H-1	Armstrong Properties	101011FTS	Repair and/or replace existing wood railing, steps and decking as needed, in kind. Repair or replace all rotten siding as needed, in kind. Replace asphalt with new asphalt shingles. Replace existing double hung one-over-one aluminum windows with new one-over-one double hung windows of the same size. Add metal storm windows, as needed.