

# LEVEL I CERTIFICATES OF APPROPRIATENESS

Historic Zoning Commission Meeting: October 17, 2019

FILE NO.	PROPERTY ADDRESS	DISTRICT	WORK DESCRIPTION
9-K-19-HZ	1121 Eleanor St. / Parcel ID 81 M H 003	Fourth and Gill H-1	<p>- Front porch: repair rotten wood on three projecting beams. Remove old patches on sides of beams, scrape away damaged wood, apply wood hardener to original beam. Apply new wood side patches. On top of projecting beams, replace asphalt shingle covering beam with either 1x pvc plank or a pressure-treated wood top covered by metal flashing. All items to be painted to match existing porch. Cap covering beam is minimally visible from the street.</p> <p>- Façade roof gable: replace rotten wood rake board in-kind. Remove rotten board, install new KDAT wood rake board. All items to be painted to match existing roof structure.</p>
10-C-19-HZ	315 Deaderick Ave. / Parcel ID 94 F K 022	Mechanicsville H-1	<p>- Replacement of non-historic exposed fastener metal roof with metal standing seam roof (Mac-Loc D concealed fastener standing seam)</p> <p>- Installation of aluminum, copper, or galvanized metal chimney cap</p>
10-B-19-HZ	509 E. Scott Ave. / Parcel ID 81 L B 027	Old North Knoxville H-1	Tuckpointing/repainting on foundation brick on side and rear elevations; repair to damaged wood siding sections on rear