



10-A-24-HZ APPLICATION FOR CERTIFICATE OF APPROPRIATENESS




1112 Gratz St. 37929

Fourth and Gill H

Original Print Date: 10/8/2024

Knoxville/Knox County Planning -- Historic Zoning Commission





Staff Report

Knoxville Historic Zoning Commission

File Number: 10-A-24-HZ

Meeting: 5/15/2025

Applicant: Dawn Irion, Beit Ventures LLC

Owner: Dawn Irion, Beit Ventures LLC

Property Information

Location: 1112 Gratz St. **Parcel ID:** 81 M F 02101

District: Fourth and Gill H

Zoning: RN-2 (Single-Family Residential Neighborhood)

Description: Craftsman, c. 1920

One-story, front-gable roof residence with an exterior of vinyl siding and a rusticated CMU foundation. Full-length front-gable roof porch.

Description of Work

Level I/II Installation of Gutters, Storm Windows/Doors, Etc, Removal of Artificial Siding, Routine Repair, Major Repair or Replacement

After-the-fact review of chimney removal. CMU chimney on left-side roof slope and stucco-clad chimney on central roof slope both removed without permits or COA. After-the-fact review of front door replacement; the front door has been replaced with a quarter-light, flat door.

Applicable Design Guidelines

Fourth and Gill Design Guidelines, adopted by the Knoxville City Council on April 20, 1999 and June 29, 1999. Roofs

3. Repair or replace roof details (chimneys, roof cresting, finials, attic vent windows, molding, and other unique roof features). Use some of these details in designing new buildings.

Masonry

- 2. Identify and preserve masonry features that define the historic character of the building, including walls, railings, columns and piers, cornices and door and window pediments.
- 3. Replace an entire masonry feature that is too deteriorated to repair. Use the remaining physical evidence to guide the new work, and match new to old. Examples can include large sections of a wall, a cornice, balustrade, column or stairway.
- 9. Chimneys should not be removed or altered if they are original and should match the original design if they must be replaced or have been removed.

Comments

N/A

Page 1 of 2 Planner in Charge: 10-A-24-HZ 5/8/2025 2:14:01 PM

Staff Findings

- 1. 1112 Gratz Street is a contributing resource to the Fourth and Gill National Register Historic District and local overlay.
- 2. The chimneys were removed without permits or a COA in early fall 2024. Review is extensively after-the-fact. The applicant then applied for a level 1 COA for various exterior rehabilitation scopes, which have been completed.
- 3. The application was postponed in October 2024. Work has continued on the property, including re-cladding the roof where the chimney was removed, and the house is currently actively listed for sale on the market.
- 4. Design guidelines clearly note that "chimneys should not be removed or altered if they are original and should match the original design if they must be replaced or have been removed." The front chimney, located on the right roof slope, may not be original to the structure; it is constructed clearly of CMU and taller and thinner than typical historic chimneys. A fireplace and mantel were located on the interior wall, indicating the chimney's location as original. Both chimneys were visible from the street. There are multiple examples of comparable chimneys on Craftsman houses in the neighborhood.
- 5. The proposed flat door does not meet the design guidelines. The applicant should select a wood Craftsman-style door and submit to staff for approval.

Staff Recommendation

Staff recommends denial of the proposed chimney removal, and reconstruction of the two chimneys, with a size and masonry design to reflect the originals or similar houses in the neighborhood, with a detail drawing for both to be submitted to be staff for review. Staff recommends denial of the installed front door, with a revised door to be submitted to staff for approval.

Page 2 of 2 Planner in Charge: 10-A-24-HZ 5/8/2025 2:14:01 PM



DESIGN REVIEW REQUEST

□ DOWNTOWN DESIGN (DK)

rtanning	DRIC ZONING (H) L HOUSING (IH)				
Beit Ventures LLC					
Applicant					
8/8/24 Octo	ber 16, 2024				
Date Filed Meet	eting Date (if applicable)		File Number(s)		
CORRESPONDENCE					
All correspondence related to this application sho	uld be directed to the	e approved contact	listed below.		
■ Owner ☐ Contractor ☐ Engineer ☐ A	rchitect/Landscape A	rchitect			
Dawn Irion	Beit Ventures LLC		С		
Name	Company				
903 Luttrell St, Unit A		Knoxville	TN	37917	
Address		City	State	Zip	
865-809-1504 daw	n@beit.llc				
Phone Emai	il				
CURRENT PROPERTY INFO					
Owner Name (if different from applicant)	Owner Address		Own	er Phone	
1112 Gratz St		081MF0)2101		
Property Address		Parcel ID)		
4th and Gill		SFR - Historic (HZ)			
Neighborhood		Zoning			
AUTHORIZATION					
Lindsay Crockett Staff Signature	Lindsay Crockett	t	9/1:	1/24	
Staff Signature	Please Print		Date	2	
Dawn Irion Digitally signed by Dawn Irion Date: 2024.08.08 16:17:27 -04	_{00'} Dawn Irion		8/8,	/24	
Applicant Signature	Please Print		Date)	

REQUEST

DOWNTOWN DESIGN	Level 1: Signs Alteration of an existing building/structure Level 2: Addition to an existing building/structure Level 3: Construction of new building/structure Site design, parking, plazas, landscape See required Downtown Design attachment for more details. Brief description of work:					
HISTORIC ZONING	Level 1: Signs Routine repair of siding, windows, roof, or other features, in-kind; Installation of gutters, storm windows/doors Level 2: Major repair, removal, or replacement of architectural elements or materials Additions and accessory structures Level 3: Construction of a new primary building Level 4: Relocation of a contributing structure Demolition of a contributing structure See required Historic Zoning attachment for more details. Brief description of work: Repair existing windows, new roof - existing roof has several locations with significant rot. Unknown at this time if the exterior wall repairs will require removal of the vinyl siding, if so will patch with wood lap siding to match what is existing. The living room chimney had significant water damage and was removed down to the mantel level - the chimney was only visible from the roof and above as was constructed of concrete block					
INFILL HOUSING						
STAFF USE ONLY	ATTACHMENTS Downtown Design Checklist Historic Zoning Design Checklist Infill Housing Design Checklist ADDITIONAL REQUIREMENTS Property Owners / Option Holders Level 1: \$50 • Level 2: \$100 • Level 3: \$250 • Level 4: \$500	FEE 1: 100.00 FEE 2: FEE 3:	TOTAL: 100.00			

Steps at rear of house are in poor condition and need to be repaired. Requesting approval to repair steps in its current size and design.

Concrete block chimneys were in poor condition and were allowing water to enter the home. Request retro-active permission for the removal of the chimneys.







Exterior photos of 1112 Gratz St March 2024



Roofing is beyond its life and is letting water into the house. Requesting approval to have the roofing replaced with architectural asphalt shingles.







